

# State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING





Michael O. Leavitt Governor Lowell P. Braxton

Division Director

PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax)

801-538-7223 (TDD)

1594 West North Temple, Suite 1210

Partial: XXX Complete: Exploration: Inspection Date & Time: 1/29/99 / 12:00p.m.-3:00p.m.

Date of Last Inspection: 12/23/98

Mine Name: Bear Canyon Mine County: Emery Permit Number: ACT/015/025						
Permittee and/or Operator's Name: Co-Op Mining Company						
Business Address: P. O. Box 1245, Huntington, Utah 84528						
Type of Mining Activity: Underground XXX Surface Prep. Plant Other						
Company Official(s): Charles Reynolds, Marlo Peterson						
State Officials(s): Peter Hess Federal Official(s): None						
Weather Conditions: Clear, Cold, 30's						
Existing Acreage: Permitted-1032.75 Disturbed-24 Regraded-0 Seeded-0 Bonded-24						
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded						
Status: _Exploration/_XXX_Active/Inactive/Temporary Cessation/Bond Forfeiture						
Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)						

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

<u>Instructions</u>

- . Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]	[]	[XX]	[]
2.	SIGNS AND MARKERS	[XX]	Ħ	[]	i i
3.	TOPSOIL	$\overline{[XX]}$	Π	īī	$\overline{\Box}$
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[XX]	$\Box$		П
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	$\Box$		$\Box$
c.	OTHER SEDIMENT CONTROL MEASURES	[XX] [XX]	$\Box$	Π	
d.	WATER MONITORING		$\Box$		
e.	EFFLUENT LIMITATIONS	$\Box$	$\Box$	$\Box$	$\Box$
5.	EXPLOSIVES	$\Box$	[_] [XX]	Π	$\Box$
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES		[XX]	$\Box$	$\Box$
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	$\Box$	Ш	Π	$\Box$
8.	NONCOAL WASTE	[XX]	ĹÌ	Ĺĺ	ĹĬ
9.	PROTECTION OF FISH, WILDLIFE AND				
	RELATED ENVIRONMENTAL VALUES	$\Box$	Ш	$\Box$	
10.	SLIDES AND OTHER DAMAGE		$\overline{[XX]}$	Π	$\Box$
11.	CONTEMPORANEOUS RECLAMATION	$\Box$	[XX]		· 🗓
12.	BACKFILLING AND GRADING	$\Box$	[XX]	$\Box$	ΞĬ
13.	REVEGETATION	$\Box$	[XX]	П	$\Box$
14.	SUBSIDENCE CONTROL	$\Box$	П	$\Box$	Π
15.	CESSATION OF OPERATIONS	$\Box$	[XX]	$\Box$	$\sqcup$
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[XX]	$\Box$	$\Box$	$\Box$
b.	DRAINAGE CONTROLS	[XX]		$\Box$	$\Box$
17.	OTHER TRANSPORTATION FACILITIES	[XX] []	$\Box$	$\Box$	$\Box$
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	<u>[XX]</u> [_]	$\Box$	[XX]	$\Box$
19.	AVS CHECK (4th Quarter-April, May, June) (date)	$\Box$	$\Box$	$\Box$	$\Box$
20.	AIR QUALITY PERMIT	ĹĬ	$\Box$	ĹĴ	ĹĬ
21.	BONDING & INSURANCE	ĪĪ	ΪÌ	ĪΪ	ĪĪ

#### INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>2</u>

PERMIT NUMBER: ACT/015/025

DATE OF INSPECTION: 1/29/99

## (Comments are Numbered to Correspond with Topics Listed Above)

## 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permittee has submitted a major permit revision which will permit the development and extraction of the Hiawatha seam and Tank seam as they exist on the east side of Bear Creek. Upon approval, these will be the Bear Canyon #3 and #4 Mines. The permittee anticipates initiating main entry development in 2000. The submittal is currently under review by the DOGM PFO and SLO.

### 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

Coal spillage exists at several of the reclaimed belt portals which are associated with the truck loading area. Most of this is washed out of the belt lines by Co-Op personnel who wash rather than shovel. Chapter 3, page 35 (3-35), under <u>Good Housekeeping</u> indicates that "spillage of coal or other materials be reduced to a minimum. Inadvertent spillage will be removed as soon as possible." The Co-Op employees who are washing these accumulations to the portal are under the misconception that these accumulations are acceptible if they are on the surface. Based on page 3-35, and 30 CFR 75.400, Accumulation of combustible materials, the permittee needs to remove these coal accumulations on a regular basis.

Copy of this Report:

Mailed to: Charles Reynolds (Co-Op)
Given to: Joe Helfrich (DOGM)
Date: February 5, 1999

Inspector's Signature:

Henry Austin (OSM)
Filed to: Price Field Office

#46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Peter Hess